



# Preliminary Information

## PIC6244D Diagnostic Aid For Vehicles All DTCs P1AEE P1AEF P1AF0 P1AF2 P1E22

Product Investigation Review Required

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2019	All	All	All	5ET50 (MKV)
Chevrolet	Malibu	2016 - 2019	All	All	All	5ET50 (MKE)
Buick	LaCrosse	2016 - 2018	All	All	LKN	5ET50 (MKV)

<b>Involved Region or Country</b>	<b>North America, Korea, China</b>
<b>Condition</b>	<b>Some customers may experience DTCs P1AEE, P1AEF, P1AF0, P1AF2, P1E22.</b>
<b>Cause</b>	<b>If all five DTCs are present, then there is an internal concern with the drive unit (transmission).  Important: If only two or three of these DTCs are present, then proceed with normal SI diagnostics as the concern may not be internal to the drive unit.</b>

### Correction:

**The drive unit (transmission) will need to be replaced.**

### Version History

<b>Version</b>	<b>5</b>
<b>Modified</b>	01/09/2017 - Created 10/17/2017 - Updated to add 2018 model Year 9/17/2018 - Updated to add 2019 model year. 10/08/2018 - To Remove Shifter to park message 7/9/2019 - Removed Reference to other Service Documents



GENERAL MOTORS